

DRESSING SCISSORS

The intended purpose of dressing scissors is cutting dressing/bandages and suture threads

TESTING AND INSPECTION:

Inspect for rust, pits, cracks, pores, and dents before use.

WARNINGS:

Don't use for a second time.

Don't use if you observe sharp edges.

Product material is conductive : Take away from electric source.

Do not use the wrong instrument, as it may cause problems during operation.

STORAGE & TRANSPORT CONDITIONS :

Ambient temperature range : 0°C to 50°C (32°F to 122°F) - Relative humidity range : 30% to 75% - Atmospheric pressure range : 700 hPA à 1060 hPA

RECYCLE:

When reprocessing medical devices please follow your local government Health & Safety procedures

Doc. # IFU-02-05/01 dated 06-03-2023


Instruction for use AA17



SURGIKARE
Toor Abad Daska Road,
Sialkot, Punjab - PK



Obelis
Bd Général Wahis, 53
B-1030 Brussels - BE



Internal drafting date 06/08/2026